

8600 Oldbridge Lane Orlando, FL 32819 mobile ph 407-733-8958

HEADER NOTES:

www.rmbaker.com rob@rmbaker.com

LOG STAGE EXPLORATORY

PERMANENT DATUM: DRILLING MEASURED FROM: LOG MEASURED FROM: GROUND SURFACE BOREHOLE RECORD USA SFWMD FROM HENDRY C-43 RESERVOIR C-43 RESERVOIR PERIMETER PIEZOMETERS 43.25 RMB RMBAKER LLC Z 50 K. SMITH **DUAL INDUCTION** 28 Mar 18 OT ELEV HDAT 4  $|\times$ VDATSIZE LIC CASING RECORD API PUMPING RATE (GPM) TROLLING DIRECTION LOGGING SPEED (FT/MIN) TYPE FLUID IN HOLE MAT. PVCFROM ALL SERVICES:
DUAL INDUCTION
NATURAL GAMMA N/A N/A N N 25 WATER 50 TO

SEC GDAT LONG

WGS84

RGE

STAT CNTY FLD

LOC COMP

CTRY PROV

LATI

NO. RUN

BIT

RECORDED BY DRILLER DEPTH-LOGGER DEPTH-DRILLER


SRVC


WITNESSED BY

RUN No DATE

TYPE LOG

LOG CODES					
3-arm caliper	CAL	long normal resistivity	RLN	deep induction conductivity	IDC
natural gamma (CPS)	GAMM	8 inch resistivity	R8	shallow induction conductivity	ISC
spontaneous potential	ESP	32 inch resistivity	R32	sonic interval velocity	DT
single point resistance	RES	deep induction resistivity	ILD	sonic porosity (RHG method)	SPHI
short normal resistivity	RSN	shallow induction resistivity	ILM	repeat designation	R





## NOTES:

While due care has been exercised in the performance of these measurements and observations, in accordance with methodologies utilized by the general practitioner, RMBAKER LLC can make no representations, warranties, or guarantees with respect to latent or concealed conditions that may exist, which may be beyond the detection capabilities of the methodologies used, or that may extend beyond the areas and depths surveyed.

warrantees, or guarantees with respect to laterit or concealed conditions that may exist, which may be beyond the detection capabilities or the methodologies dised, or that may exist do be provided in detection capabilities or the methodologies dised, or that may exist disease and deput sources.

The geophysical well logs show subsurface conditions as they existed at the dates and locations shown, and it is not warranted that they are representative of subsurface conditions at other locations and times. If, at any time, different subsurface conditions from those observed are determined to be present, we must be advised and allowed to review and revise our observations if necessary.

Florida Licensed Geology Business GB 458

## **END OF LOG**