RMBAKER LLC WELL CAUSD Geology and Geophysics UWI CAUSD

8600 Oldbridge Lane Orlando, FL 32819

rob@rmbaker.com mobile ph 407-733-8958

COMP

RMBAKER LLC

LOC

www.rmbaker.com HEADER NOTES:
THE BOREHOLE WAS BLOCKED AT 60 FEET.

LOG STAGE EXPLORA

	UP N/A	WATER 20	ALL SERVICES: DUAL INDUCTION NATURAL GAMMA		(PLORATORY
TO 80			TCES: JCTION GAMMA		DRY
		LOG CODES	S		
3-arm caliper	CAL	long normal resistivity	RLN	deep induction conductivity	IDC
natural gamma (CPS)	GAMM	8 inch resistivity	R8	shallow induction conductivity	ISC
spontaneous potential	ESP	32 inch resistivity	R32	sonic interval velocity	DT
single point resistance	RES	deep induction resistivity	ILD	sonic porosity (RHG method)	SPHI
		shallow induction resistivity	ILM	repeat designation	R

RUN NO.

BIT

FROM

TO

SIZE

MAT. PVC

FROM

CASING RECORD

BOREHOLE RECORD

WITNESSED BY

E. GEDDES RMBAKER LLC

API

RECORDED BY DRILLER DEPTH-LOGGER

RMB

DEPTH-DRILLER

80

OBSTRUCTED

SRVC

DATE

19 Nov 15

LOG MEASURED FROM: GROUND SURFACE

DRILLING MEASURED FROM:

RUN No

TYPE LOG

DUAL INDUCTION

PUMPING RATE (GPM) TROLLING DIRECTION LOGGING SPEED (FT/MIN) TYPE FLUID IN HOLE RGE SEC GDAT LONG

PERMANENT DATUM:

STAT CNTY

끋 **USA**

FLD

MARTIN


CAULKINS WATER FARM CAULKINS WATER FARM


LATI CTRY PROV

WGS84

HDAT \prec

ELEV V DAT





While due care has been exercised in the performance of these measurements and observations, in accordance with methodologies utilized by the general practitioner, RMBAKER LLC can make no representations, warranties, or guarantees with respect to latent or concealed conditions that may exist, which may be beyond the detection capabilities of the methodologies used, or that may extend beyond the areas and depths surveyed.

The geophysical well logs show subsurface conditions as they existed at the dates and locations shown, and it is not warranted that they are representative of subsurface conditions and times.

If, at any time, different subsurface conditions from those observed are determined to be present, we must be advised and allowed to review and revise our observations if necessary.

Florida Licensed Geology Business GB 458