

8600 Oldbridge Lane Orlando, FL 32819 mobile ph 407-733-8958

www.rmbaker.com rob@rmbaker.com

FLD COMP LOC SFWMD WATER CONSERVATION AREA 2

STAT CNTY

BROWARD

卍

CTRY PROV

USA

LATI

26.3090 -80.3570

4 $|\times$

WATER CONSERVATION AREA 2 **DUAL INDUCTION** HEADER NOTES: ELEV HDAT VDATSIZE LIC CASING RECORD API PUMPING RATE (GPM) TROLLING DIRECTION LOGGING SPEED (FT/MIN) TYPE FLUID IN HOLE LOG STAGE COMPLETION PVCMAT. FROM ALL SERVICES:
DUAL INDUCTION
NATURAL GAMMA N/A UP N/A 25 Z X WATER 124.24 TO

 $_{\rm dML}$ SEC GDAT LONG

WGS84

RGE

PERMANENT DATUM:

RUN No DATE DRILLING MEASURED FROM:

25 Sep 18

LOG MEASURED FROM: TOP OF CASING

TYPE LOG

NO. RUN

BIT

FROM

OT

BOREHOLE RECORD

WITNESSED BY

SFWMD


RMBAKER


RMB N N 124.24

125

SRVC RECORDED BY DRILLER DEPTH-LOGGER **DEPTH-DRILLER**

LOG CODES					
3-arm caliper	CAL	long normal resistivity	RLN	deep induction conductivity	IDC
natural gamma (CPS)	GAMM	8 inch resistivity	R8	shallow induction conductivity	ISC
spontaneous potential	ESP	32 inch resistivity	R32	sonic interval velocity	DT
single point resistance	RES	deep induction resistivity	ILD	sonic porosity (RHG method)	SPHI
short normal resistivity	RSN	shallow induction resistivity	ILM	repeat designation	R





While due care has been exercised in the performance of these measurements and observations, in accordance with methodologies utilized by the general practitioner, RMBAKER LLC can make no representations, warranties, or guarantees with respect to latent or concealed conditions that may exist, which may be beyond the detection capabilities of the methodologies used, or that may extend beyond the areas and depths surveyed.

The geophysical well logs show subsurface conditions as they existed at the dates and locations shown, and it is not warranted that they are representative of subsurface conditions at other locations and times. If, at any time, different subsurface conditions from those observed are determined to be present, we must be advised and allowed to review and revise our observations if necessary.

Florida Licensed Geology Business GB 458

END OF LOG