

8600 Oldbridge Lane Orlando, FL 32819

www.rmbaker.com rob@rmbaker.com mobile ph 407-733-8958

CASING SCREEN FROM 120.8 FT TO 125.3 FT

HEADER NOTES:

COMP

LOC

LOG STAGE EXPLORATORY

근 RMBAKER LLC **GLADES GLADES COUNTY GLADES COUNTY** 

PROV STAT CNTY FLD


RGE SEC GDAT LONG CTRY PERMANENT DATUM: LATI LOG MEASURED FROM: GROUND SURFACE WGS84 -81.046180 26.819900 USA ELEV H DAT ĸ × V DAT ALL SERVICES:


DUAL INDUCTION


NATURAL GAMMA
ACOUSTIC TELEVIEWER
VIDEO


DRILLING MEASURED FROM:


DNIEERO MEASONED FROM:	Y.						
DATE	15 Jul 14		TYPE FLUID IN HOLE	IN HOLE		WATER	
RUN No	1		S SOUS SOUR	LOGGING SPEED (FT/MIN)		20	
TYPELOG	COMPOSITE		TROLLING DIRECTION	DIRECTION	_	UP	
			PUMPING RATE (GPM)	ATE (GPM)			
DEPTH-DRILLER							
DEPTH-LOGGER	130.7						
DRILLER							
RECORDED BY	RMB						
SRVC	RMBAKER LLC	С	API		_	N/A	
WITNESSED BY	K. SMITH		LIC			N/A	
RUN BOREHOLE RECORD	RD .		CASING RECORD	CORD			
NO. BIT FROM		TO	SIZE	MAT.	FROM		ТО
			2	PVC	0		130.7




















While due care has been exercised in the performance of these measurements and observations, in accordance with methodologies utilized by the general practitioner, RMBAKER LLC can make no representations, warranties, or guarantees with respect to latent or concealed conditions that may exist, which may be beyond the detection capabilities of the methodologies used, or that may extend beyond the areas and depths surveyed.

The geophysical well logs show subsurface conditions as they existed at the dates and locations shown, and it is not warranted that they are representative of subsurface conditions at other locations and times.

If, at any time, different subsurface conditions from those observed are determined to be present, we must be advised and allowed to review and revise our observations if necessary.

Certificate of Authorization GB 458