



# Everglades Nutrient Removal Area

## Site 103



# Everglades Nutrient Removal Area Site 103 Ext.



**2 Inch PVC Monitoring  
Well ¾ Inch Piezometer  
Located Within Aluminum  
Housing**



DRAWING NAME:	enr103a.dwg
DRAWN BY:	JLW DATE: 4/98
REVISED BY:	DATE:
HYDROGEOLOGY	DIVISION 705
SOUTH FLORIDA WATER MGMT. DIST.	

# Everglades Nutrient Removal Area Site 103

