

A photograph of a rusty metal container, possibly a fuel tank or a storage can, lying on its side in a field of dry, yellowish-brown grass. The container has a flat, circular lid with a silver metal lock mechanism attached to its left side. The lid is heavily rusted and shows some faint, illegible markings. The container is positioned vertically in the center of the frame, with the lid at the top. The background is a dense field of dry grass, with some green blades visible on the right side.

UNKNOWN LOCK

SF6-UA-2048 OKLFW-33 AND 34

2003. 11. 10



33 34

METAL CASING  
AND UNKNOWN LOCK

SF6-UA-2048 OKLEW-33  
FACING SOUTHWEST

2003. 11. 10



AIRPORT SERVICE ROAD



METAL CASING  
AROUND WELL  
AND UNKNOWN LOCK

OKLFW 33 AND 34

SF6-UA-2048 OKLFW-33  
FACING NORTH

2003. 11. 10