



SF6-UA-2020  
OKLEW-35

2003.12.17





BROKEN WELL COVER

UNKNOWN  
LOCK

BROKEN METAL CASING  
AROUND WELL

INFESTED WITH ANTS INSIDE  
METAL CASING

SF6-UA-2020 OKLFW-35  
CLOSE UP

2003.11.10



SF6-UA-2020  
FACING EAST  
OKLFW-35



2003.12.17





SF6-UA-2020 OKLFW-35  
FACING NORTH

OKLFW-35 IS AT LAND SURFACE

2003. 11. 10



SF6-UA-2020 OKLFW-35  
FACING SOUTH

MW 35

2003.11.10



SF6-UA-2020  
FACING WEST

OKLFW-35



2003.12.17