

**Southern Golden Gate Estates Restoration  
Monitoring Well Bench Mark Elevations**

<b>Well &amp; Bench Names</b>	<b>Bench Mark Elevation</b>	<b>Well Head Elevations</b>	<b>CORPSCON</b>
	NAVD 88	NAVD 88	
SGT1W1	9.23	13.71	1.33
SGT1W2	10.20	14.81	1.33
SGT1W4	10.17	14.24	1.34
SGT1W5	10.92	15.01	1.34
SGT2W1	9.56	13.48	1.32
SGT2W2	9.27	14.20	1.33
SGT2W3	7.22	10.74	1.33
SGT2W4	9.76	13.45	1.34
SGT2W5	9.44	14.47	1.35
SGT2W6	8.68	13.52	1.35
SGT3W1	5.49	9.73	1.32
SGT3W2	6.32	9.21	1.32
SGT3W3	5.65	10.01	1.33
SGT3W4	6.86	12.04	1.34
SGT3W5	7.58	11.41	1.34
SGT3W6	6.77	11.57	1.35
SGT3W7	8.82	13.45	1.35
SGT4W1	4.81	8.97	1.32
SGT4W2	5.73	9.34	1.32
SGT4W3	4.56	6.91	1.33
SGT4W4(R598)*	4.47	9.80	1.33
SGT4W5	4.53	9.66	1.33
SGT4W6	5.91	10.10	1.34

All Elevations are NAVD 88

**Corpscon values taken from Corpscon 6.0.1  
with the 05.txt file added.**

**This data is  
"NOT PART OF THE SURVEY DATA PROVIDED  
BY THE CONTRACTOR."**

\* This Bench Mark is a  
previously set CERP  
Monument and does not  
have a SGT stamping