




8600 Oldbridge Lane Orlando, FL 32819 mobile ph 407-733-8958


LOG STAGE EXPLORATORY


;						
COMP	RMBAKER LLC	Ċ.				
LOC	GLADES COUNTY	YTN				
FLD	GLADES COUNTY	YTN				
CNTY	GLADES					
STAT	콘					
PROV	콘					
CTRY	USA					
LATI 26.827820	20	X			ALL SERVICES:	TCES:
LONG -81.536870	870	Υ			CALIPER	
GDAT WGS84		HDAT			DUAL INDUCTION	JCTION
SEC		ELEV			ELECTRIC	LOG
TWP		VDAT			VIDEO	
RGE					, 1	
PERMANENT DATUM:	M:					
LOG MEASURED FR	LOG MEASURED FROM: GROUND SURFACE	Ж				
7.475	16 1.11 11		TVDE EI III	TYPE ELLIN IN HOLE	W/ATED	
RIN No			I OGGING	OGGING SPEED (ET/MIN)		
TYPE LOG	COMPOSITE		TROLLING	TROLLING DIRECTION		
			PUMPING	PUMPING RATE (GPM)		
DEPTH-DRILLER						
DEPTH-LOGGER	121.7					
DRILLER						
RECORDED BY	RMB					
SRVC	RMBAKER LLC	LC	API		N/A	
WITNESSED BY	K. SMITH		LIC		N/A	
RUN BOREHOL	BOREHOLE RECORD		CASING RECORD	ECORD		
	FROM	OT	SIZE	MAT.	FROM	TO
1 9.875	60	121.7	10	STEEL	0	60

















NOTES:

While due care has been exercised in the performance of these measurements and observations, in accordance with methodologies utilized by the general practitioner, RMBAKER LLC can make no representations, warranties, or guarantees with respect to latent or concealed conditions that may exist, which may be beyond the detection capabilities of the methodologies used, or that may extend beyond the areas and depths surveyed.

The geophysical well logs show subsurface conditions as they existed at the dates and locations shown, and it is not warranted that they are representative of subsurface conditions at other locations and times.

If, at any time, different subsurface conditions from those observed are determined to be present, we must be advised and allowed to review and revise our observations if necessary.

Certificate of Authorization GB 458

END OF LOG